



| | |
|------------------|----|
| PFI 0/P0.0 (In) | 1 |
| PFI 1/P0.1 (In) | 2 |
| PFI 2/P0.2 (In) | 3 |
| PFI 3/P0.3 (In) | 4 |
| D GND | 5 |
| PFI 4/P1.0 (Out) | 6 |
| PFI 5/P1.1 (Out) | 7 |
| PFI 6/P1.2 (Out) | 8 |
| PFI 7/P1.3 (Out) | 9 |
| +5 V | 10 |
| D GND | 11 |
| AO 0 | 12 |
| AO 1 | 13 |
| AO GND | 14 |
| AI 0 | 15 |
| AI 8 | 16 |
| AI 1 | 17 |
| AI 9 | 18 |
| AI 2 | 19 |
| AI 10 | 20 |
| AI 3 | 21 |
| AI 11 | 22 |
| AI SENSE | 23 |
| AI 4 | 24 |
| AI 12 | 25 |
| AI 5 | 26 |
| AI 13 | 27 |
| AI GND | 28 |
| AI 6 | 29 |
| AI 14 | 30 |
| AI 7 | 31 |
| AI 15 | 32 |

Figure 3. USB-6211/6215 Pinout